



## Service Information Letter

<b>SIL Number:</b>	606-00000-004		
<b>To:</b>	Avidyne Dealers		
<b>Subject:</b>	MLB100		
<b>Purpose:</b>	This Service Information Letter (SIL) advises owners, operators, and installers that the MLB100 may not provide traffic information.		
<b>Revision:</b>	00	<b>Date:</b>	10/23/15

### Effectivity:

<b>Description</b>	MLB100
<b>Avidyne Part Number</b>	200-00270-000

### Problem Description:

This Service Information Letter advises installers, owners, and operators that the MLB100 ADS-B receiver may not send traffic information to the Avidyne IFD540/440 or Garmin 430/530.

During initial power-on of the MLB100 it has been reported that the MLB100 does not send traffic information to the display until the MLB100 power is cycled off and back on.

### Recommended Action:

After the powering on the IFD540/440 or Garmin 430/530 and the MLB100 and you confirmed your own ship symbol on the moving map is aligned to current GPS position, recycle MLB100 power by resetting the MLB100 circuit breaker.

### Solution:

Avidyne is investigating the cause of the issue. Avidyne will provide further information regarding this issue as it becomes available.