

Service Information Letter

SIL Number:	606-00083-017		
То:	Owners/Operators of Avidyne Release 9 in Cirrus SR2X		
Subject:	Release 9 Cirrus SR2X AFMS Amendment - Load Shedding		
Purpose:	This Service Information Letter (SIL) advises owners and operators of Avidyne Release 9 installed in Cirrus SR2x aircraft of the availability of a revised AFMS that includes load shedding procedures for dual alternator failure.		
Revision:	00	Date:	05/11/2015

Effectivity:

Description	Release 9	
Avidyne Part Number	700-00183-XXX (Release 9 Integrated Flight Displays)	
Avidyne Software Release	Release 9 – all versions	
Aircraft Installation	Cirrus SR2X	

Issue Description:

This Service Information Letter (SIL) advises owners and operators of Avidyne Release 9 of a revised Airplane Flight Manual Supplement (AFMS) that contains emergency procedures that include specific load shedding, in the event of a dual alternator failure.

Required Pilot Actions

All operators of Cirrus SR2X airplanes modified with Avidyne STC SA00282BO (Avidyne Entegra Release 9) must replace the existing approved airplane flight manual supplement (AFMS)

600-00712-002, Rev01

FAA Approved Airplane Flight Manual Supplement For Cirrus Design Corporation Model SR20/SR22 and SR22 when modified per STC SA10588SC (Tornado Alley turbo-normalizer) with Avidyne Integrated Flight Displays p/n 700-00083-XXX and Control Display Unit p/n 700-00150-XXX with s/w Release 9.3 (or later approved revision)

with revision 01 of the same document.

Revision 00 606-00083-017 Date: 05/11/2015 Page 1 of 2



Service Information Letter

Document Availability

Avidyne supplement **600-00712-002**, **Rev01** can be obtained by contacting Avidyne directly or may be downloaded from the Avidyne dealer website http://dealers.avidyne.com/files/downloads/600-00712-002.pdf

Contact Information:

For any questions regarding this Service Information Letter please contact Avidyne Technical Support at:

1-888-723-7592 Toll Free US 1-781-402-7592 International Direct Dial techsupport@avidyne.com www.avidyne.com/support

Avidyne Corporation 55 Old Bedford Road Lincoln, MA 01773

Revision 00 606-00083-017 Date: 05/11/2015 Page 2 of 2