



# Service Information Letter

<b>SIL Number:</b>	606-00212-000		
<b>To:</b>	Installers of Vantage 12		
<b>Subject:</b>	Replace unsigned AFMS		
<b>Purpose:</b>	To replace the unsigned AFMS with the signed AFMS		
<b>Revision:</b>	00	<b>Date:</b>	09/29/2025

**Effectivity:**

<b>Description</b>	Vantage 12
<b>Avidyne Part Number</b>	700-00212-XXX
<b>Avidyne Software Release</b>	N/A

**Issue Description:**

The current AFMS available is not signed by the FAA, this has raised questions on whether the aircraft post installation can be returned to service without a signed version of the AFMS

**Recommended Installer Actions:**

Replace unsigned AFMS for the now available signed AFMS for STC SA12084BO.

**Contact Information:**

For any questions regarding this Service Information Letter please contact Avidyne Technical Support at

1-888-723-7592 Toll Free USA

+1-781-402-7592 International Direct Dial

[techsupport@avidyne.com](mailto:techsupport@avidyne.com)

[www.avidyne.com/support](http://www.avidyne.com/support)